



# TASK CARD

TASK CARD No: 20-00-00-001

TASK CARD Rev: 04

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
1

TO BE PERFORMED BY:

AVIONICS

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

28-41-07-213-801-A/600

ACCESS:

MEN: 2

M/H: 1.92

SKILL:

MEN: 2

M/H: 1.2

REQ. TOOLS:

REQ MATERIAL:

ZONE:

521 531 621 631

PANELS:

521AB 521BB 521DB 521EB 531AB 531BB 531CB 531DB 531EB 531FB 531GB 531HB 621AB 621BB 621DB  
621EB 631AB 631BB 631CB 631DB 631EB 631FB 631GB 631HB

TASK DESCRIPTION:

Tank Unit Wiring and Tank Unit Wiring Connections

Detailed Inspection of Tank Unit wiring, Tank Unit wiring connections and electrical bonding features inside Wing Tank.

NOTE: EWIS. This task complies with the Fuel Tank Safety Requirement.

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

PLANING DEPARTMENT

TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE



# TASK CARD

TASK CARD No: 20-00-00-002

TASK CARD Rev: 04

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
2

TO BE PERFORMED BY:

AVIONICS

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

28-41-07-213-802-A

ACCESS: MEN: 2  
M/H: 0.64

SKILL:

MEN: 2  
M/H: 1.2

REQ. TOOLS:

REQ MATERIAL:

ZONE:

143 144 192

PANELS:

143AL 143BL 143CL 144AR 144BR 144CR 192BL 192CR

TASK DESCRIPTION:

Tank Unit Wiring and Tank Unit Wiring Connections, inside Wing Stub Main Box

Detailed Inspection of Tank Unit wiring, Tank Unit wiring connections and electrical bonding features inside Wing Stub Tank.

NOTE: EWIS. This task complies with the Fuel Tank Safety Requirement.

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

PLANING DEPARTMENT

TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE



# TASK CARD

TASK CARD No: 20-00-00-003

TASK CARD Rev: 12

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
3

TO BE PERFORMED BY:

AVIONICS

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

AMM 28-41-00-213-801-A/600

ACCESS:

MEN:

M/H:

SKILL:

MEN:

2

M/H:

0.92

REQ. TOOLS:

REQ MATERIAL:

ZONE:

147 198 1431 1441

PANELS:

198AR 198DR 147AL

TASK DESCRIPTION:

DET - Fuel Quantity Gauging System Harness and Connectors

Detailed Inspection of Fuel Quantity Gauging System Harness and Connectors.  
Examine installation, protection, segregation, identification, chaffing and superficial insulation damages of harness and connectors in the Fuel Tank adjacent areas and electronic Bay.

NOTE: This task complies with the Fuel Tank Safety Requirement.

NOTE: Interval is 18000 fh.

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

PLANING DEPARTMENT

TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE



# TASK CARD

TASK CARD No: 20-00-00-004

TASK CARD Rev: 12

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
4

TO BE PERFORMED BY:

AVIONICS

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

AMM 28-25-01-213-801-A/600

ACCESS:

MEN:

M/H:

SKILL:

MEN:

2

M/H:

0.45

REQ. TOOLS:

REQ MATERIAL:

ZONE:

123 147 192 199

PANELS:

123BL 147AL 192AL 192BR 199AL

TASK DESCRIPTION:

DET - Fuel Pump Connector

Detailed Inspection of Fuel Pump Connectors. Examine for electrical arcing signals, pins corrosion/discoloration and fuel leakage through the connector.

NOTE: This task complies with the Fuel Tank Safety Requirement.

NOTE: Interval is 18000 fh.

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

PLANING DEPARTMENT

TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE





# TASK CARD

TASK CARD No: 20-00-00-005

TASK CARD Rev: 04

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
5

TO BE PERFORMED BY:

AES

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

AMM 53-20-00-100-801-A/700

ACCESS:

MEN:

M/H:

SKILL:

MEN:

1

M/H:

0.27

REQ. TOOLS:

REQ MATERIAL:

ZONE:

125 126 131 132 141 142 1491 1492

PANELS:

125BLF 125AZ 125ALW 125BZ 26ARF 126AZ 126ARW 131DLF 131FLF 131ALW 131BLW 131CLW 131BZ  
131CZ 131DZ 131HLF 131EZ 132BRF 132CRF 132ARW 132BRW 132CRW 132BZ 132CZ 141ALW 141BLW  
141BZ 141CZ 141DZ 142ARW 142BRW

TASK DESCRIPTION:

FORWARD PRESSURE BULKHEAD, FORWARD, CENTER I AND II FUSELAGE BOTTOM  
AREAS - INTERNALCleaning the Entire Area (Side and Bottom Areas) Covered by the Cargo Compartment  
Linings.

NOTE: EWIS.

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

PLANING DEPARTMENT

TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE



# TASK CARD

TASK CARD No: 20-00-00-006

TASK CARD Rev: 04

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
6

TO BE PERFORMED BY:

AES

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

AMM 53-20-00-100-802-A/700

ACCESS:

MEN:

M/H:

SKILL:

MEN:

2

M/H:

0.27

REQ. TOOLS:

REQ MATERIAL:

ZONE:

147 148 151 152

PANELS:

147BLF 147ALW 147BLW 147DLF 148ARF 148ARW 148BRW 148BRF 151BLF 151DLF 151FLF 151HLF 151ALW  
151BLW 151CLW 152ARF 152BRF 152CRF 152ARW 152BRW

TASK DESCRIPTION:

CENTER FUSELAGE II AND III AND AFT CARGO CPT - INTERNAL

Cleaning the Entire Area (Side and Bottom Areas) Covered by the Cargo Compartment Linings.

NOTE: EWIS.

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

PLANING DEPARTMENT

TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE



# TASK CARD

TASK CARD No: 20-Z100-003

TASK CARD Rev: 03

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
7

TO BE PERFORMED BY:

AVIONICS

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

AMM 05-21-00-211-853-A/600

ACCESS:

MEN:

M/H:

SKILL:

MEN:

1

M/H:

0.99

REQ. TOOLS:

REQ MATERIAL:

ZONE:

125 126 131 132 141 142 1491 1492

PANELS:

125AL 125AZ 125ALC 125BZ 126AZ 126ARW 131ALC 131BLC 131CLC 131DLC 131ALW 131BLW 131CLW  
131BZ 131CZ 131DZ 131ELC 131EZ 132ARW 132BRW 132CRW 141ALW 141BLW 141ALC 141AZ141BLC  
141CLC 141BZ 141CZ 141DZ 142ARW 142BRW 142AZ

TASK DESCRIPTION:

EWIS COMPONENTS OF ELECTRICAL AND APU POWER HARNESS

General Visual Inspection of EWIS components of APU Generation Power Cable and Electrical Power Distribution Harness at FWD Cargo Compartment for signs of damage, adequate installation, chafing and general condition.

EWIS components of electrical and APU power harness are located at FWD fuselage bottom rear area, center fuselage I and II bottom area at FWD cargo compartment, FWD pressure bulkhead FWD face, including areas covered by cargo compartment ceiling.

INTERVAL : 18000 FH

NOTE: EWIS.

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

PLANING DEPARTMENT

TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE



# TASK CARD

TASK CARD No: 20-Z120-001

TASK CARD Rev: 04

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
8

TO BE PERFORMED BY:

AVIONICS

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

05-21-00-211-854-A/600

ACCESS:

MEN:

M/H:

SKILL:

MEN:

1

M/H:

0.99

REQ. TOOLS:

REQ MATERIAL:

ZONE:

121 122 123 124 125 126

PANELS:

123BL 125AZ 126AZ

TASK DESCRIPTION:

EWIS COMPONENTS OF FWD PRESSURE BULKHEAD AFT FACE, FWD FUSELAGE  
BOTTOM PORTION (AHEAD THE COCKPIT PARTITION) HARNESS - INTERNAL

General Visual Inspection of EWIS components of Electrical Power  
Distribution, AC External Power, FWD Avionics Power Supply and Main  
Batteries Harness at FWD Avionics Compartment for signs of damage, adequate  
installation, chafing and general condition.  
EWIS components are located on FWD pressure bulkhead AFT face, FWD fuselage  
bottom portion (ahead the cockpit partition), and nose landing gear wheel well areas  
harness - INTERNAL  
INTERVAL: 18000 FH  
NOTE: EWIS.

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

PLANING DEPARTMENT

TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE





# TASK CARD

TASK CARD No: 20-Z140-011

TASK CARD Rev: 03

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
9

TO BE PERFORMED BY:

AVIONICS

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

05-21-00-100-802-A/700

ACCESS:

MEN:

M/H:

SKILL:

MEN:

1

M/H:

0.99

REQ. TOOLS:

REQ MATERIAL:

ZONE:

147 148 1493 1494 199

PANELS:

147AL 147AZ 148AZ 199AL

TASK DESCRIPTION:

CENTER FUSELAGE II CENTER E-BAY AREA AND AFT PRESS BULKHEAD AFT FACE -  
INTERNALCleaning of Center E-Bay Area and Aft Pressure Bulkhead Aft Face at Center Fuselage  
II - Inside Center E-Bay.

INTERVAL : 18000 FH

NOTE: EWIS.

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

PLANING DEPARTMENT

TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE



# TASK CARD

TASK CARD No: 20-Z150-002

TASK CARD Rev: 07

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
10

TO BE PERFORMED BY:

AVIONICS

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

05-21-00-211-842-A/600

ACCESS:

MEN:

M/H:

SKILL:

MEN:

1

M/H:

0.99

REQ. TOOLS:

REQ MATERIAL:

ZONE:

151 152 251 252

PANELS:

SEE MPD-2515, EMBRAER 190/195

TASK DESCRIPTION:

EWIS COMPONENTS AT AFT CARGO COMPARTMENT AREA HARNESS.

General Visual Inspection of EWIS components of APU Power Generator and Electrical Power Distribution Harness at AFT Cargo Compartment for signs of damage, adequate installation, chafing and general condition.

INTERNAL: 18000 FH

NOTE: EWIS.

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

PLANING DEPARTMENT

TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE



# TASK CARD

TASK CARD No: 20-Z150-005

TASK CARD Rev: 03

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
11

TO BE PERFORMED BY:

AVIONICS

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

05-21-00-211-868-A/600

ACCESS:

MEN:

M/H:

SKILL:

MEN:

1

M/H:

0.99

REQ. TOOLS:

REQ MATERIAL:

ZONE:

151 152

PANELS:

151BZ 152BZ

TASK DESCRIPTION:

EWIS COMPONENTS OF APU POWER GENERATOR HARNESS AND EPD HARNESS

General Visual Inspection of EWIS components of APU Power Generator Harness and Electrical Power Distribution Harness at Center Fuselage III lower portion, behind AFT cargo compartment AFT partition for signs of damage, adequate installation, chafing and general condition.

INTERVAL: 18000 FH

NOTE: EWIS.

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

# PLANING DEPARTMENT

## TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE



# TASK CARD

TASK CARD No: 20-Z150-007

TASK CARD Rev: 03

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
12

TO BE PERFORMED BY:

AVIONICS

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

05-21-00-100-811-A/700

ACCESS:

MEN:

M/H:

SKILL:

MEN:

1

M/H:

0.99

REQ. TOOLS:

REQ MATERIAL:

ZONE:

151 152

PANELS:

151BZ 152BZ

TASK DESCRIPTION:

CENTER FUSELAGE III LOWER PORTION - INTERNAL

Cleaning of Center Fuselage III Lower Portion, Behind Aft Cargo Compartment Aft Partition and from Fr 85 to Fr 90/91 - Internal Side of Fuselage.

INTERVAL: 18000 FH

NOTE: EWIS.

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

PLANING DEPARTMENT

TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE





# TASK CARD

TASK CARD No: 20-Z220-007

TASK CARD Rev: 03

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
13

TO BE PERFORMED BY:

AVIONICS

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

AMM 05-21-00-100-803-A/700

ACCESS:

MEN:

M/H:

SKILL:

MEN:

1

M/H:

0.99

REQ. TOOLS:

REQ MATERIAL:

ZONE:

223 224

PANELS:

223ALC 223BLC 224ARC

TASK DESCRIPTION:

WINDSHIELD AND DIRECT VISION WINDOWS SURROUNDING - INTERNAL

Cleaning of Windshield and Direct Vision Surroundings and Cockpit Ceiling Areas -  
Internal Side of Cockpit.

INTERVAL: 18000 FH

NOTE: EWIS.

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

PLANING DEPARTMENT

TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE



# TASK CARD

TASK CARD No: 20-Z220-008

TASK CARD Rev: 03

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
14

TO BE PERFORMED BY:

AVIONICS

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

05-21-00-100-805-A/700

ACCESS:

MEN:

M/H:

SKILL:

MEN:

1

M/H:

0.99

REQ. TOOLS:

REQ MATERIAL:

ZONE:

220 221 222

PANELS:

221DZ 221EZ 221FZ 221GZ 221HZ 221JZ 221KZ 221LZ 221SZ 222DZ 222EZ 222FZ 222GZ 222HZ 222JZ  
222KZ 222LZ

TASK DESCRIPTION:

PANELS, GLARESHIELD, CENTRAL CONSOLE, YOKE AND PEDALS AREAS - INTERNAL

Cleaning of Cockpit Main Instrument Panel, Control Pedestal, Yoke and Pedals Areas -  
Internal Side of Cockpit.

INTERVAL: 18000 FH

NOTE: EWIS.

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

PLANING DEPARTMENT

TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE



# TASK CARD

TASK CARD No: 20-Z700-003

TASK CARD Rev: 12

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
15

TO BE PERFORMED BY:

AVIONICS

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

AMM 05-26-00-212-801-A/600

ACCESS:

MEN:

M/H:

SKILL:

MEN:

1

M/H:

0.76

REQ. TOOLS:

REQ MATERIAL:

ZONE:

1431 1441 1493 1494

PANELS:

TASK DESCRIPTION:

GVI - EWIS COMPONENTS OF MAIN LANDING GEAR BAY HARNESS

General Visual Inspection of EWIS components of IDG, Engine and Fuel System Harness at Main Landing Gear Bay for signs of damage, adequate installation, chafing and general condition.

INTERVAL: 18000 FH

NOTE: EWIS.

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

PLANING DEPARTMENT

TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE



# TASK CARD

TASK CARD No: 25-02-250-H001

TASK CARD Rev: 03

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
16

TO BE PERFORMED BY:

AVIONICS

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

25-20-04-210-801-A/600

ACCESS:	MEN: 1	SKILL:	MEN: 1	REQ. TOOLS:
	M/H: 0.04		M/H: 0.24	REQ MATERIAL:

ZONE:

252

PANELS:

252AZ

TASK DESCRIPTION:

Aft Electronics Compartment Access Door EMI shield and Bonding Jumper

Aft-Electronic-Compartment Access-Door EMI-Shield and Bonding Jumper - General Visual Inspection

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

PLANING DEPARTMENT

TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE





# TASK CARD

TASK CARD No: 28-50-00-007

TASK CARD Rev: 12

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
17

TO BE PERFORMED BY:

AES

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

AMM 28-21-00-211-801-A/600

ACCESS:

MEN:

M/H:

SKILL:

MEN:

1

M/H:

0.66

REQ. TOOLS:

REQ MATERIAL:

ZONE:

143 144 192 193 194

PANELS:

192BL, 192CR, 143AL, 143BL, 143CL, 144AR, 144BR, 144CR

TASK DESCRIPTION:

GVI - FLEXIBLE CONNECTIONS, JUMPERS, CLAMPS AND FLANGES AT WING STUB

General Visual Inspection of Flexible Connections, Jumpers, Clamps and Flanges at Wing Stub. Examine for excessive wearing, and adequate installation.

NOTE: This task complies with the Fuel Tank Safety Requirement.

NOTE: Interval is 18000 fh.

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

PLANING DEPARTMENT

TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE



# TASK CARD

TASK CARD No: 28-50-00-014

TASK CARD Rev: 12

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
18

TO BE PERFORMED BY:

AES

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

AMM 28-21-00-211-802-A/600

ACCESS:

MEN:

M/H:

SKILL:

MEN:

1

M/H:

1.34

REQ. TOOLS:

REQ MATERIAL:

ZONE:

521 531 621 631

PANELS:

521AB, 521BB, 521DB, 521EB, 531AB, 531BB, 531CB, 531DB, 531EB, 531FB, 531GB, 531HB  
621AB, 621BB, 621DB, 621EB, 631AB, 631BB, 631CB, 631DB, 631EB, 631FB, 631GB, 631HB

TASK DESCRIPTION:

GVI - FLEXIBLE CONNECTIONS, JUMPERS, CLAMPS AND FLANGES AT WING MAIN BOX

General Visual Inspection of Flexible Connections, Jumpers, Clamps and Flanges at Wing Main Box. Examine for excessive wearing, and adequate installation.

NOTE: This task complies with the Fuel Tank Safety Requirement.

NOTE: Interval is 18000 fh.

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

PLANING DEPARTMENT

TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE



# TASK CARD

TASK CARD No: 31-01-220-H001

TASK CARD Rev: 03

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
19

TO BE PERFORMED BY:

AVIONICS

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

31-61-01-210-801-A/600

ACCESS:

MEN: 1  
M/H: 0

SKILL:

MEN: 1  
M/H: 0.91

REQ. TOOLS:

REQ MATERIAL:

ZONE:

221 222

PANELS:

TASK DESCRIPTION:

MFD, PFD AND EICAS DISPLAYS CONNECTORS, 360s METALLIC BACKSHELL, TAG RING  
AND ELECTRICAL BONDING

Display Units - General Visual Inspection

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

PLANING DEPARTMENT

TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE



# TASK CARD

TASK CARD No: Z100-003

TASK CARD Rev: 04

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
20

TO BE PERFORMED BY:

AES

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

AMM 05-21-00-211-804-B/600

ACCESS:

MEN: 1

M/H: 5.2

SKILL:

MEN: 1

M/H: 0.83

REQ. TOOLS:

REQ MATERIAL:

YES

ZONE:

125 126 131 132 141 142 1491 1492

PANELS:

125ALW 125BLF 126ARF 126ARW 131ALW 131BLW 131CLW 131DLF 131FLF 132ARW 132BRF 132BRW  
132CRF 132CRW 141ALW 141AZ 141BLW 142ARW 142AZ 142BRW

TASK DESCRIPTION:

GVI - FWD FUSELAGE BOTTOM REAR AREA,CENTER FUSELAGE I AND II BOTTOM AREA  
AT FWD CARGO COMPARTMENT, FWD PRESSURE BULKHEAD FWD FACE - INTERNALGeneral Visual Inspection of Fwd Fuselage Bottom Rear Area, Center Fuselage I and II  
Bottom Areas at Cargo Compartment (Except area between Wing Stub and Floor  
Panels), including Center Fuselage II Fwd Pressure Bulkhead Fwd Face, areas covered  
by Cargo Compartment Ceiling and Center Floor Structure - Internal Side of FuselageNOTE: EWIS. Floor boards removal not required  
INTERVAL: 18000 FH

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

# PLANING DEPARTMENT

## TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE Z100-003

### MATERIALS

1. Methyl Ethyl Ketone QTY: JM:  
ASTM-D-740





# TASK CARD

TASK CARD No: Z111-001

TASK CARD Rev: 04

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
21

TO BE PERFORMED BY:

AES

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

AMM 05-21-00-211-803-A/600

ACCESS:

MEN: 1

M/H: 0.04

SKILL:

MEN: 1

M/H: 0

REQ. TOOLS:

REQ MATERIAL:

YES

ZONE:

111

PANELS:

TASK DESCRIPTION:

FORWARD PRESSURE BULKHEAD AND RADOME - INTERNAL

General Visual Inspection of Fwd Pressure Bulkhead Fwd Face and Radome - Internal

INTERVAL : 18000 FH

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

# PLANING DEPARTMENT

## TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE Z111-001

### MATERIALS

1. Methyl Ethyl Ketone QTY: JM:  
ASTM-D-740



# TASK CARD

TASK CARD No: Z124-001

TASK CARD Rev: 04

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
22

TO BE PERFORMED BY:

AES

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

AMM 05-21-00-211-821-A/600

ACCESS:

MEN: 1  
M/H: 0.56

SKILL:

MEN: 1  
M/H: 1.33

REQ. TOOLS: YES

REQ MATERIAL: YES

ZONE:

123 124

PANELS:

TASK DESCRIPTION:

GVI - RAM-AIR-TURBINE (RAT) COMPARTMENT - INTERNAL

General Visual Inspection of Ram-Air-Turbine (RAT) Compartment - Internal Side of RAT Compartment.

NOTE: EWIS. RAT has to be deployed.

INTERVAL : 18000 FH

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

# PLANING DEPARTMENT

## TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE Z124-001

### MATERIALS

1. Methyl Ethyl Ketone QTY: JM:  
ASTM-D-740

### TOOLS/EQUIPMENTS

1. COVER - RAT BLADE  
GSE 068
2. PIN - STOW LOCK  
GSE 189



# TASK CARD

TASK CARD No: Z140-002

TASK CARD Rev: 04

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
23

TO BE PERFORMED BY:

AES

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

AMM 05-24-00-211-808-A/600

ACCESS:	MEN: 1	SKILL:	MEN: 1	REQ. TOOLS:
	M/H: 0.7		M/H: 9.3	REQ MATERIAL: YES

ZONE:

143 144 192

PANELS:

TASK DESCRIPTION:

GVI - WING STUB MAIN BOX - INTERNAL

General Visual Inspection of Wing Stub Main Box - Internal Side of Wing Stub.

NOTE: EWIS.

NOTE: Task interval changed in Rev01 of CMP iaw Temp.rev.2-7 of MRBR.

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

# PLANING DEPARTMENT

## TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE Z140-002

### MATERIALS

1. Anti-Fungus Compound Solvent QTY: JM:  
AMS-C-27725



# TASK CARD

TASK CARD No: Z150-002

TASK CARD Rev: 07

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
24

TO BE PERFORMED BY:

AES

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

AMM 05-21-00-211-805-B/600

ACCESS:	MEN: 1	SKILL:	MEN: 1	REQ. TOOLS:
	M/H: 4.3		M/H: 4.17	REQ MATERIAL: YES

ZONE:

147 148 151 152

PANELS:

TASK DESCRIPTION:

AFT CARGO COMPARTMENT AREA - INTERNAL

General Visual Inspection at Aft Cargo Compartment Area - Internal Side of Fuselage.

NOTE: EWIS.

INTERVAL : 18000 FH

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

# PLANING DEPARTMENT

## TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE Z150-002

### MATERIALS

1. Methyl Ethyl Ketone QTY: JM:  
ASTM-D-740





# TASK CARD

TASK CARD No: Z220-001

TASK CARD Rev: 04

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
25

TO BE PERFORMED BY:

AES

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

AMM 05-21-00-211-808-A/600

ACCESS:

MEN: 2

M/H: 3.4

SKILL:

MEN: 2

M/H: 6.32

REQ. TOOLS:

REQ MATERIAL:

YES

ZONE:

221 222 223 224

PANELS:

TASK DESCRIPTION:

GVI -WINDSHIELD AND DIRECT VISION WINDOWS SURROUNDING AND COCKPIT  
CEILING AREAS - INTERNALGeneral Visual Inspection of Windshield and Direct Vision Surroundings and Cockpit  
Ceiling Areas - Internal Side of Cockpit.

NOTE: EWIS.

INTERVAL: 18000 FH

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

# PLANING DEPARTMENT

## TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE Z220-001

### MATERIALS

1. Methyl Ethyl Ketone QTY: JM:  
ASTM-D-740



# TASK CARD

TASK CARD No: Z220-003

TASK CARD Rev: 04

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
26

TO BE PERFORMED BY:

AES

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

AMM 05-21-00-211-811-B/600

ACCESS:	MEN: 1	SKILL:	MEN: 1	REQ. TOOLS:
	M/H: 1.56		M/H: 3	REQ MATERIAL: YES

ZONE:

221 222

PANELS:

TASK DESCRIPTION:

GVI - PANELS, GLARESHIELD, CENTRAL CONSOLE, YOKE AND PEDALS AREAS - INTERNAL

General Visual Inspection of Cockpit Main Instrument Panel, Control Pedestal, Yoke and Pedals Areas - Internal Side of Cockpit.

NOTE: EWIS.

INTERVAL: 18000 FH

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

# PLANING DEPARTMENT

## TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE Z220-003

### MATERIALS

1. Methyl Ethyl Ketone QTY: JM:  
ASTM-D-740



# TASK CARD

TASK CARD No: Z300-001

TASK CARD Rev: 05

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
27

TO BE PERFORMED BY:

AES

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

AMM 05-21-00-212-806-A/600

ACCESS:	MEN: 1	SKILL:	MEN: 1	REQ. TOOLS:
	M/H: 0.12		M/H: 1.59	REQ MATERIAL: YES

ZONE:

123 147 199 313 314 315 316 317 318 351

PANELS:

123BL 147AL 199AL

TASK DESCRIPTION:

REAR FUSELAGE AND TAIL CONE - EXTERNAL

General Visual Inspection of Rear Fuselage and Tail Cone, Without Fairings Removed - External Side of Fuselage and Tail Cone.

INTERVAL: 18000 FH

CERTIFY:	DOUBLE INSP. CERTIFY:

NOTE:

# PLANING DEPARTMENT

## TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE Z300-001

### MATERIALS

1. Methyl Ethyl Ketone QTY: JM:  
ASTM-D-740



# TASK CARD

TASK CARD No: Z320-002

TASK CARD Rev: 04

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
28

TO BE PERFORMED BY:

AES

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

AMM 05-22-00-211-803-B/600

ACCESS:

MEN: 1

M/H: 2.58

SKILL:

MEN: 1

M/H: 1.24

REQ. TOOLS:

REQ MATERIAL:

YES

ZONE:

123 147 199 253 254 317 318 321 322 323 324 325 326 327

PANELS:

TASK DESCRIPTION:

GVI - VERTICAL STABILIZER, VERTICAL STABILIZER FAIRINGS, VERTICAL STABILIZER ROOT AREA, CENTER FUSELAGE III AND REAR FUSELAGE UPPER SKIN COVERED BY VERTICAL STABILIZER FAIRINGS - INTERNAL

General Visual Inspection of Vertical Stabilizer Leading Edge, Rudder Leading Edge, Dorsal Fin, Tip Fairings and Fuselage in the Region Covered by Vertical Stabilizer Fairings - Internal Side of Stabilizer and Fairings.

NOTE: EWIS.

INTERVAL: 18000 FH

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

# PLANING DEPARTMENT

## TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE Z320-002

### MATERIALS

1. Methyl Ethyl Ketone QTY: JM:  
ASTM-D-740





# TASK CARD

TASK CARD No: Z330-002

TASK CARD Rev: 12

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
29

TO BE PERFORMED BY:

AES

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

AMM 05-22-00-211-801-B/600

ACCESS:

MEN:

M/H:

SKILL:

MEN:

1

M/H:

0.92

REQ. TOOLS:

REQ MATERIAL:

YES

ZONE:

123 147 199 331 334 335 337 338 341 344 345 347 348

PANELS:

123BL 147AL 199AL 331AL 331BL 334AB 334BB 334CB 334DB 334EB 334FB 334GB 334HB 334JB 334KB  
334LB 334MB 334NB 334PB 334QB 334RB 335AL 341AR 341BR 344AB 344BB 344CB 344DB 344EB 344FB  
344GB 344HB 344JB 344KB 344LB 344MB 344NB 344PB 344QB 344RB 345AR

TASK DESCRIPTION:

GVI - HORIZONTAL STABILIZER, HORIZONTAL STABILIZER FAIRINGS (LEADING EDGE AND TIPS) - INTERNAL

General Visual Inspection of LH/RH Horizontal Stabilizer, Leading Edge, and Tip Fairings - Internal Side of Stabilizer and Fairings.

NOTE: EWIS.

NOTE: Interval is 18000 FH.

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

# PLANING DEPARTMENT

## TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE Z330-002

### MATERIALS

1. Methyl Ethyl Ketone QTY: JM:  
ASTM-D-740



# TASK CARD

TASK CARD No: Z330-003

TASK CARD Rev: 13

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
30

TO BE PERFORMED BY:

AES

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

AMM 05-22-00-211-802-B/600

ACCESS:

MEN:

M/H:

SKILL:

MEN:

2

M/H:

1.66

REQ. TOOLS:

REQ MATERIAL:

YES

ZONE:

315, 316, 317, 318, 332, 333, 336, 342, 343, 346, 123, 147, 199

PANELS:

TASK DESCRIPTION:

HORIZONTAL STABILIZER FAIRINGS (SLIDING PLATE AND FAIRING), REAR FUSELAGE SKIN COVERED BY HORIZONTAL STABILIZER FAIRINGS - INTERNAL

Horizontal Stabilizer Fairings (Sliding Plate and Fairing), Rear Fuselage Skin Covered by Horizontal Stabilizer Fairings - Internal General Visual Inspection

INTERVAL: 18000 FH

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

# PLANING DEPARTMENT

## TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE Z330-003

### MATERIALS

1. Methyl Ethyl Ketone QTY: JM:  
ASTM-D-740



# TASK CARD

TASK CARD No: Z500-003

TASK CARD Rev: 04

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
31

TO BE PERFORMED BY:

AES

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

05-24-00-211-801-B/600

ACCESS:	MEN: 1	SKILL:	MEN: 1	REQ. TOOLS:
	M/H: 1.52		M/H: 2.5	REQ MATERIAL: YES

ZONE:

123 147 199 521 531 621 631

PANELS:

TASK DESCRIPTION:

GVI - WING MAIN BOX FROM RIB 1 TO RIB 23 - INTERNAL

General Visual Inspection of Wing Main Box from Rib 1 to Rib 23 - Internal side of Wing Main Box.

NOTE: EWIS.

INTERVAL: 18000 FH

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

# PLANING DEPARTMENT

## TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE Z500-003

### MATERIALS

1. Methyl Ethyl Ketone QTY: JM:  
ASTM-D-740



# TASK CARD

TASK CARD No: Z813-002

TASK CARD Rev: 04

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
32

TO BE PERFORMED BY:

AES

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

05-25-00-211-807-A/600

ACCESS:

MEN: 1

M/H: 0

SKILL:

MEN: 1

M/H: 0.67

REQ. TOOLS:

REQ MATERIAL:

YES

ZONE:

813

PANELS:

TASK DESCRIPTION:

GVI - LEFT OVERWING DOOR - INTERNAL

General Visual Inspection of LH Overwing Door - Internal Side of Door.

NOTE: Door has to be opened.

INTERVAL 18000 FH

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

# PLANING DEPARTMENT

## TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE Z813-002

### MATERIALS

1. Methyl Ethyl Ketone QTY: JM:  
ASTM-D-740





# TASK CARD

TASK CARD No: Z825-002

TASK CARD Rev: 04

A/C  
40-AOCWP  
WO-AOC-1801WP DATE  
01.07.2017STATION  
/SEQ  
33

TO BE PERFORMED BY:

AES

CERTIFY LEVEL: B

DOUBLE INSPECTION:

NO

CERTIFY LEVEL:

JOB CARD:

JOB PROCEDURE:

05-25-00-211-808-A/600

ACCESS:

MEN: 1

M/H: 0

SKILL:

MEN: 1

M/H: 0.67

REQ. TOOLS:

REQ MATERIAL:

YES

ZONE:

825

PANELS:

TASK DESCRIPTION:

GVI - RIGHT OVERWING DOOR - INTERNAL

General Visual Inspection of Right Overwing Door - Internal Side of Door.

NOTE: Door has to be opened.

INTERVAL: 18000 FH

CERTIFY:

DOUBLE  
INSP.  
CERTIFY:

NOTE:

# PLANING DEPARTMENT

## TOOLS CARD PARTS/TOOLING REQUIREMENTS

MP REFERENCE Z825-002

### MATERIALS

1. Methyl Ethyl Ketone QTY: JM:  
ASTM-D-740