



WORKPACK ACCOUNTABILITY FORM

WP Number WO-AOM-2277

WP Date 05.04.2018

Description

8YR Check

Station

/

AC Reg. Mark

4O-AOM

PAGE

1

SEQ	Task Card / EO	Task Card / EO Description	Certify	NOTE
1	K062112-00-01 170	<p>KEEL/CENTER SECTION Carry out general visual inspection of belly fairings area, internally.</p> <p>NOTE: MLG doors to be opened.</p> <p>NOTE 2: Task interval changed from 12000 FH to 6YR iaw MRB revision 14. Task has to be accomplished at the first convenient opportunity but not exceeding the interval of 6 YR counting from date of MRB Revision 14 publication - 01.10.2011.</p> <p>NOTE3: INTERVAL: 6YR</p> <p>NOTE4: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
2	K062114-00-01 170	<p>KEEL/CENTER SECTION Carry out general visual inspection of under floor area of passenger compartment, internally. (EZAP)</p> <p>NOTE: Remove Floor panels.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
3	K062116-00-01 173	<p>FUSELAGE TO WING FAIRING Carry out general visual inspection of LH fuselage to wing fairings, internally.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
4	K062116-00-01 174	<p>FUSELAGE TO WING FAIRING Carry out general visual inspection of RH fuselage to wing fairing, internally.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
5	K062306-00-01 320	<p>FUSELAGE TAIL SECTION Carry out general visual inspection of fuselage tail section, internally.</p> <p>NOTE: 1. Open speed brakes 2. Particular attention to be paid to the areas around the lightening holes for cracking.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
6	K281500-00-01 523	<p>FUEL TANK VENTILATION Carry out inspection of ventilation drain float valve.</p> <p>NOTE: Interval coincides with the structural internal tank inspection.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		



WORKPACK ACCOUNTABILITY FORM

WP Number WO-AOM-2277

WP Date 05.04.2018

Description

8YR Check

Station

/

AC Reg. Mark

40-AOM

PAGE

2

SEQ	Task Card / EO	Task Card / EO Description	Certify	NOTE
7	K281500-00-01 623	<p>FUEL TANK VENTILATION Carry out inspection of ventilation drain float valve.</p> <p>NOTE: Interval coincides with the structural internal tank inspection.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
8	K284500-00-01 225	<p>COLLECTOR TANK LEVEL WARNING Perform operational check of collector tank low level warning.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
9	K351100-00-09 240	<p>OXYGEN MASK DETAILED INSPECTION OF THE SMOKE GOGGLES</p> <p>INTERVAL : 6 YR</p> <p>NOTE: New task in REV 09 of CMP, initial compliance date is the date of the previous 6yr inspection, not the date of task compliance.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
10	K352100-00-04 200	<p>PASSENGER OXYGEN Carry out Detailed inspection of oxygen masks.</p> <p>NOTE: Oxygen panels to be opened.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
11	K521252-00-01 811	<p>PASSENGER DOOR, INT Carry out general visual inspection of passenger door, closure frames internal, closure beams internal, internal frames, beams, intercostals and inner skin both sides.</p> <p>NOTE: Door cover escape slide to be removed.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
12	K523351-00-02 820	<p>LARGE CARGO DOOR, INT Carry out general visual inspection of large cargo doors inner skin, internal frames and intercostals.</p> <p>NOTE: Door covers and sound proofing to be removed.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		



WORKPACK ACCOUNTABILITY FORM

WP Number WO-AOM-2277

WP Date 05.04.2018

Description

8YR Check

Station

/

AC Reg. Mark

40-AOM

PAGE

3

SEQ	Task Card / EO	Task Card / EO Description	Certify	NOTE
13	K523352-00-01 820	<p>LARGE CARGO DOOR, EXT Carry out general visual inspection of large cargo doors piano hinge.</p> <p>NOTE: Can be combined with task K062102-00-01.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
14	K523353-00-01 820	<p>LARGE CARGO DOORS, EXT Carry out general visual inspection of large cargo doors hook latches and hook latch support brackets.</p> <p>NOTE: This task is not applicable to the center cargo door if MBLS is installed.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
15	K524152-00-01 821	<p>FWD S/E DOOR, INT Carry out general visual inspection of FWD S/E door inner frames, beams, intercostals and inner skin from both sides.</p> <p>NOTE: Door cover to be removed.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
16	K531004-00-01 120	<p>FWD FUSELAGE, INT Carry out general visual inspection of nose landing gear bay top and side panels from cabin side.</p> <p>NOTE: Center floor panels between STA 2550 and STA 3870 to be removed. Soundproofing to be removed as far as required.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
17	K531013-00-01 128	<p>FWD FUSELAGE, INT Carry out general visual inspection of forward service/emergency door opening lower torsion box, rear side of frame at STA 3870 and front side of frame at STA 4610, both between floor level and STR 50.</p> <p>NOTE: Lining panels, sound proofing and interior panels to be removed as far as required.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
18	K531016-00-01 110	<p>FWD FUSELAGE, INT Carry out general visual inspection of front side of forward pressure bulkhead including connection angles.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		



WORKPACK ACCOUNTABILITY FORM

WP Number WO-AOM-2277

WP Date 05.04.2018

Description

8YR Check

Station

/

AC Reg. Mark

4O-AOM

PAGE

4

SEQ	Task Card / EO	Task Card / EO Description	Certify	NOTE
19	K531020-00-01 210	<p>FWD FUSELAGE, INT Carry out general visual inspection of lower window grider and lower parts of window post 2 and 3 below sliding windows.</p> <p>NOTE: Side panels below sliding windows and soundproofing to be removed as far as required.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
20	K531024-00-01 126	<p>FWD FUSELAGE, INT Carry out general visual inspection of NLG strut pressure box.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
21	K531027-00-01 261	<p>FWD FUSELAGE, INT Carry out general visual inspection of passenger door opening lower torsion box, rear side of frame at STA 3870 and front side of frame at STA 4850, both between floor level and STR 31.</p> <p>NOTE: Perform this task in zones 261,120 and 131.</p> <p>NOTE: SOUND PROOFING AND COVERS TO BE REMOVED AS FAR AS REQUIRED.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
22	K533004-00-01 280	<p>CENTER FUSELAGE, INT Carry out general visual inspection of fuselage skin internal, between STR 19/56 and centerwing/wheelbay top cover and between STA 14911 and STA 18451, including longeron at WL-536.</p> <p>NOTE: Seats, lining panels and sound proofing to be removed as far as required.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
23	K533005-00-01 160	<p>CENTER FUSELAGE, INT Carry out general visual inspection of re-inforced STR 2 and STR 73 and keel beam extension brackets between STA 11257 and STA 14911 including attachments to pressure bulkhead at STA 14911.</p> <p>NOTE: Cargo compartment lining and sound proofing to be removed as far as required. If mechanical loading system (effectivity ORC Z0042) installed, center part to be removed.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		



WORKPACK ACCOUNTABILITY FORM

WP Number WO-AOM-2277

WP Date 05.04.2018

Description

8YR Check

Station

/

AC Reg. Mark

4O-AOM

PAGE

5

SEQ	Task Card / EO	Task Card / EO Description	Certify	NOTE
24	K533008-00-02 280	CENTER FUSELAGE, INT Carry out general visual inspection of lower part of main frame at STA 17011(below STR 19/56). NOTE: Seats, lining panels and floor panels to be removed as far as required. NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		
25	K533009-00-01 280	CENTER FUSELAGE, INT Carry out general visual inspection of overwing emergency exit opening lower beam box and frames between STA14911 and STA 17011, between STR26A/48A and centre wing top skin. NOTE: Can be combined with task: K062114-00-01 NOTE: Overwing emergency exits, seats, luggage bins, sound proofing and floor panels to be removed as far as required. NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		
26	K533024-00-01 100	CENTER FUSELAGE, EXT Carry out general visual inspection of flaptrack attachment lugs at STA 18451 NOTE: Can be combined with task K062116-00-01. NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		
27	K534105-00-01 190	REAR FUSELAGE, INT Carry out general visual inspection of partial bulkhead at STA 23586 below STR 16/59(floor level). NOTE: Cargo compartment lining to be removed as far as required. NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		
28	K534107-00-01 199	REAR FUSELAGE, INT Carry out general visual inspection of front side of rear pressure bulkhead, including connection angles, below STR 16/59(floor level). NOTE: Cargo compartment lining, sound proofing, chilling units and ducts to be removed as far as required. NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		
29	K534108-00-01 310	REAR FUSELAGE ,INT Carry out general visual inspection of rear side of rear pressure bulkhead including connection angles, vertical support beams at BL 425 LH/RH and BL 1050 LH/RH, excluding engine support fittings. NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		



WORKPACK ACCOUNTABILITY FORM

WP Number WO-AOM-2277

WP Date 05.04.2018

Description

8YR Check

Station

/

AC Reg. Mark

40-AOM

PAGE

6

SEQ	Task Card / EO	Task Card / EO Description	Certify	NOTE
30	K534124-00-01 194	<p>REAR FUSELAGE, INT Carry out general visual inspection of rear cargo door opening upper torsion box, frames at STA 20778 and STA 22236, both between STR 60 and STR 74, beam at STR 72 between STA 20320 and STA 22706 and hooklatch fitting back-up brackets.</p> <p>NOTE: Lining panels, seats, cabine side panels and sound proofing to be removed as far as required.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
31	K534201-00-01 320	<p>TAIL SECTION, INT Carry out detailed inspection of frame at STA 26026.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
32	K544203-00-01 432	<p>NACELLE, INT Carry out general visual inspection of forward engine mount fitting link assy, including chatter proof bolt assemblies.</p> <p>NOTE: Can be combined with task K062401-00-02 and task K062403-00-01.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
33	K544203-00-01 442	<p>NACELLE, INT Carry out general visual inspection of forward engine mount fitting link assy, including chatter proof bolt assemblies.</p> <p>NOTE: Can be combined with task K062401-00-02 and task K062403-00-01.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
34	K544204-00-01 432	<p>NACELLE, INT Carry out general visual inspection of forward engine mount fitting link assy, including chatter proof bolt assemblies.</p> <p>NOTE: Can be combined with task K062401-00-02 and task K062403-00-01.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
35	K544204-00-01 442	<p>NACELLE, INT Carry out general visual inspection of aft engine mount fitting link assy, including chatter proof bolt assemblies.</p> <p>NOTE: Can be combined with task K062401-00-02 and task K062403-00-01.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		



WORKPACK ACCOUNTABILITY FORM

WP Number WO-AOM-2277

WP Date 05.04.2018

Description

8YR Check

Station

/

AC Reg. Mark

40-AOM

PAGE

7

SEQ	Task Card / EO	Task Card / EO Description	Certify	NOTE
36	K544301-00-01 432	NACELLE, INT Carry out general visual inspection of forward and aft end of thrust of strut assy. NOTE: Can be combined with task K062401-00-02 and task K062403-00-01. NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		
37	K544301-00-01 442	NACELLE, INT Carry out general visual inspection of forward and aft end of thrust strut assy. NOTE: Can be combined with task K062401-00-02 and task K062403-00-01. NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		
38	K551009-00-02 339	HOR. STABILIZER Carry out general visual inspection of horizontal stabilizer junction fitting lugs. NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		
39	K551011-00-03 340	HOR. STABILIZER, INT Carry out general visual inspection of horizontal stabilizer pivot point lugs and pivot bolts. NOTE: Pivot bolts not to be removed. NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		
40	K551012-00-02 356	HOR. STABILIZER, INT Carry out general visual inspection of elevator support arms outside shrouds at rib 1265, rib 2505 and rib 4070 and bearing support brackets at rib 215 and rib 4350. NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		
41	K551012-00-02 366	HOR. STABILIZER, INT Carry out general visual inspection of elevator support arms outside shrouds at rib 1265, rib 2505 and rib 4070 and bearing support brackets at rib 215 and rib 4350. NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		
42	K552001-00-01 359	ELEVATOR, INT Carry out general visual inspection of elevator main spar front side at hinges 1,2 and 3. NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		



WORKPACK ACCOUNTABILITY FORM

WP Number WO-AOM-2277

WP Date 05.04.2018

Description

8YR Check

Station

/

AC Reg. Mark

4O-AOM

PAGE

8

SEQ	Task Card / EO	Task Card / EO Description	Certify	NOTE
43	K552001-00-01 369	ELEVATOR, INT Carry out general visual inspection of elevator main spar front side at hinges 1,2 and 3. NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		
44	K552002-00-02 359	ELEVATOR, INT Carry out general visual inspection of elevator root rib and tip rib (including hinge 4) from outside torsion box only. Hinge bracket and adjacent nose ribs at stabilizer STA 1231.65, STA 2548.52 and STA 4190.45 and support shaft. NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		
45	K552002-00-02 369	ELEVATOR, INT Carry out general visual inspection of elevator root rib and tip rib (including hinge 4) from outside torsion box only. Hinge bracket and adjacent nose ribs at stabilizer STA 1231.65, STA 2548.52 and STA 4190.45 and support shaft. NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		
46	K553006-00-02 330	VERTICAL STABILIZER, INT Carry out general visual inspection of horizontal stabilizer pivot lug area (external only). NOTE: Can be combined with task K062308-00-01. NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		
47	K571010-00-01 170	CENTER WING, INTERNAL Carry out detailed inspection of center wing lower skin lower surface and stringers between rib 1700LH and RH. NOTE: Bleed air pipe to be removed and MLG doors to be opened. NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		
48	K571011-00-01 100	CENTER WING Carry out general visual inspection of center wing front spar end fitting. Outside fuselage contour from front side. NOTE: Can be combined with task K062116-00-01. NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		



WORKPACK ACCOUNTABILITY FORM

WP Number WO-AOM-2277

WP Date 05.04.2018

Description

8YR Check

Station

/

AC Reg. Mark

40-AOM

PAGE

9

SEQ	Task Card / EO	Task Card / EO Description	Certify	NOTE
49	K571016-00-01 170	CENTER WING, EXTERNAL Carry out general visual inspection of center wing to outer wing attachment lower side external including joint strip and attachment to adjacent structure. NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		
50	K572002-00-01 520	OUTER WING, INTERNAL Carry out general visual inspection of outer wing front spar rear side between WS 1825 and WS 11190. NOTE: Removable part of rib 2230 to be removed. NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		
51	K572002-00-01 620	OUTER WING, INTERNAL Carry out general visual inspection of outer wing front spar rear side between WS 1825 and WS 11190. NOTE: Removable part of rib 2230 to be removed. NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		
52	K572006-00-01 520	OUTER WING, INTERNAL Carry out general visual inspection of outer wing rear spar front side between WS 1825 and WS 11190. NOTE: Removable part of rib 2230 to be removed. NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		
53	K572006-00-01 620	OUTER WING, INTERNAL Carry out general visual inspection of outer wing rear spar front side between WS 1825 and WS 11190. NOTE: Removable part of rib 2230 to be removed . NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		
54	K572011-00-01 522	OUTER WING, INTERNAL Carry out general visual inspection of outer wing end rib at WS 1825 outboard side and outer wing rib at WS 2230 both sides. NOTE: Removable part of rib 2230 to be removed. NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		
55	K572011-00-01 622	OUTER WING, INTERNAL Carry out general visual inspection of outer wing end rib at WS 1825 outboard side and outer wing rib at WS 2230 both sides. NOTE: Removable part of rib 2230 to be removed. NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.		



WORKPACK ACCOUNTABILITY FORM

WP Number WO-AOM-2277

WP Date 05.04.2018

Description

8YR Check

Station

/

AC Reg. Mark

4O-AOM

PAGE

10

SEQ	Task Card / EO	Task Card / EO Description	Certify	NOTE
56	K572012-00-01 520	<p>OUTER WING, INTERNAL Carry out general visual inspection of outer wing forged rib at WS 2635 on both sides.</p> <p>NOTE: Removable part of rib 2230 to be removed.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
57	K572012-00-01 620	<p>OUTER WING, INTERNAL Carry out general visual inspection of outer wing forged rib at WS 2635 on both sides.</p> <p>NOTE: Removable part of rib 2230 to be removed.</p> <p>NOTE: Interval changed from 6YR to 8YR iaw MRB Rev.14 TR ESC-05.</p>		
58	K572013-00-01 520	<p>OUTER WING, INTERNAL Carry out general visual inspection of outer wing ribs between WS 3100 and WS 10550 (both sides) and rib at WS 11190 (inboard side only).</p> <p>NOTE: Task interval changed from 6yr to 8yr iaw MRB TR ESC-05</p>		
59	K572013-00-01 620	<p>OUTER WING, INTERNAL Carry out general visual inspection of outer wing ribs between WS 3100 and WS 10550 (both sides) and rib at WS 11190 (inboard side only).</p> <p>NOTE: Task interval changed from 6yr to 8yr iaw MRB TR ESC-05.</p>		
60	K572016-00-01 520	<p>OUTER WING, INTERNAL Carry out general visual inspection of outer wing torsion box upper skin internal including stringers between front spar and rear spar between WS 1825 and WS 11190.</p> <p>NOTE: Task interval changed from 6yr to 8yr iaw MRB TR ESC-05.</p>		
61	K572016-00-01 620	<p>OUTER WING, INTERNAL Carry out general visual inspection of outer wing torsion box upper skin internal including stringers between front spar and rear spar between WS 1825 and WS 11190.</p> <p>NOTE: Task interval changed from 6yr to 8yr iaw MRB TR ESC-05.</p>		
62	K572019-00-02 520	<p>OUTER WING, INTERNAL Carry out detailed inspection of outerwing fuel tank access rebates, internal.</p> <p>NOTE: Task interval changed from 6yr to 8yr iaw MRB TR ESC-05.</p>		



WORKPACK ACCOUNTABILITY FORM

WP Number WO-AOM-2277

WP Date 05.04.2018

Description

8YR Check

Station

/

AC Reg. Mark

4O-AOM

PAGE

11

SEQ	Task Card / EO	Task Card / EO Description	Certify	NOTE
63	K572019-00-02 620	<p>OUTER WING, INTERNAL Carry out detailed inspection of outerwing fuel tank access rebates, internal.</p> <p>NOTE: Task interval changed from 6yr to 8yr iaw MRB TR ESC-05.</p>		
64	K572034-00-01 530	<p>OUTER WING, INTERNAL Carry out general visual inspection of flap track beam at WS 5280 and WS 8200 including: -Both sides of track beam (box structure) externally. -Flap track fitting on outer wing rear spar and attachments to flap track beam.</p> <p>NOTE: Task interval changed from 6yr to 8yr iaw MRB TR ESC-05</p>		
65	K572034-00-01 630	<p>OUTER WING, INTERNAL Carry out general visual inspection of flap track beam at WS 5280 and WS 8200 including: -Both sides of track beam (box structure) externally. -Flap track fitting on outer wing rear spar and attachments to flap track beam.</p> <p>NOTE: Task interval changed from 6yr to 8yr iaw MRB TR ESC-05</p>		
66	K572034-00-02 530	<p>OUTER WING, INTERNAL Carry out general visual inspection of flap track rails and vane rails at flap track beam of WS 5280 and WS 8200.</p> <p>NOTE: Task interval changed from 6yr to 8yr iaw MRB TR ESC-05</p>		
67	K572034-00-02 630	<p>OUTER WING, INTERNAL Carry out general visual inspection of flap track rails and vane rails at flap track beam of WS 5280 and WS 8200.</p> <p>NOTE: Task interval changed from 6yr to 8yr iaw MRB TR ESC-05</p>		
68	K575305-00-01 543	<p>INNER FLAP, INTERNAL Carry out general visual inspection of inner flap rib at WS 2043, forward of front spar, and ribs at WS 2388 and WS 4426.</p> <p>NOTE: Flaps to be fully extended.</p> <p>NOTE: Task interval changed from 6yr to 8yr iaw MRB TR ESC-05</p>		
69	K575305-00-01 643	<p>INNER FLAP, INTERNAL Carry out general visual inspection of inner flap rib at WS 2043, forward of front spar, and ribs at WS 2388 and WS 4426.</p> <p>NOTE: Flaps to be fully extended.</p> <p>NOTE: Task interval changed from 6yr to 8yr iaw MRB TR ESC-05</p>		



WORKPACK ACCOUNTABILITY FORM

WP Number WO-AOM-2277

WP Date 05.04.2018

Description

8YR Check

Station

/

AC Reg. Mark

40-AOM

PAGE

12

SEQ	Task Card / EO	Task Card / EO Description	Certify	NOTE
70	K575405-00-01 544	<p>OUTER FLAP, INTERNAL Carry out general visual inspection of outer flap rib at WS 5654 forward of front spar, ribs at WS 5965 and WS 7559.</p> <p>NOTE: Flaps to fully extended.</p> <p>NOTE: Task interval changed from 6yr to 8yr iaw MRB TR ESC-05</p>		
71	K575405-00-01 644	<p>OUTER FLAP, INTERNAL Carry out general visual inspection of outer flap rib at WS 5654 forward of front spar, ribs at WS 5965 and WS 7559.</p> <p>NOTE: Flaps to fully extended.</p> <p>NOTE: Task interval changed from 6yr to 8yr iaw MRB TR ESC-05</p>		